Introduction

The Allied Telesyn AT-2450FTX Fast Ethernet adapter card offers a reliable and cost-effective means of connecting a computer to a 100Mbps Fast Ethernet or 10Mbps Ethernet network and the internet. This PCI-bus product provides true plug-and-play connection and excellent performance in either 10Mbps or 100Mbps (copper) or 10Mbps (fiber) network segments.

Package Checklist

The Allied Telesyn AT-2450FTX includes:

- 1 AT-2450FTX Fast Ethernet Adapter Card
- 1 CardAssistant driver CD
- · 1 user guide

System Requirements

The AT-2450FTX Fast Ethernet adapter card requires the following basic host PC features:

- A host PC that supports PCI-bus peripheral cards
 16 MB of RAM
- Microsoft Windows (2000, 98, 95, NT 3.5x or 4.0, or Windows for Workgroups 3.11)

You also need to provide the following items:

- A 100Mbps Fast Ethernet or 10Mbps Ethernet (copper segment) or 10Mbps Ethernet (fiber segment) local area network (LAN)
- 1 standard twisted-pair cable (Category 3 or above for 10Mbps operation; Category 5 for 100Mbps operation), 100 m maximum length or 1 standard 62.5/125 µm fiber cable with supported connectors (twe ST or SC)

Installation-Windows 2000 / Windows 9x

IMPORTANT—DO NOT INSERT THE ADAPTER CARD UNTIL YOU HAVE RUN WINPREP (Step 1, below). If you installed the adapter and without running WINPREP—and booted your computer—see the box "I tyou inserted the card BEFORE running WINPREP..."

These instructions assume Windows 2000, Windows 98, or Windows 95 is installed according to your computer's documentation. For the majority of applications, installing the AT-2450FTX Fast Ethernet adapter card involves running WINPREPEXE and plugging the adapter card into a PCI slot in your computer. The driver files for the AT-2450FTX adapter card are installed by Windows during the next boot.

1 Run WINPREP

Insert the CardAssistant CD. Choose "AT-2450FTX" and then choose "WINPREP". (If Autorun CD feature of Windows is disabled, the menu screen does not come up. In this case, browse to the folder "DRIVERSIATI2450_2700" on the CD-ROM drive and run the WINFREPEXE application.) WINFREP AUTOMATES

the installation process, preparing Windows for the adapter card by copying driver files to your hard drive. When WINPREP finishes copying files to the proper directories, choose "Shutdown" (Windows 98 or 95) or "Exti" (Windows 2000).

2 Install the Adapter Card

WARNING—High voltages inside the computer present a safety hearand. Adds sure the power is of flepfor removing the cover. This LAN adapter card is for use only with IBM or compatible UI-listed personal computers that have installation instructions detailing installation of PCI periphriend. Installation installation of with precautions to prevent damage to static-sensitive components. Follow your computer's instruction manual for specific information on installing peripheral devices in your computer. Once the adapter card is seated in a PCI slot and the computer's cover is back on, plug in the cable, turn on the power, and reboot into Windows.

Important cable considerations: Copper—The AT-2450FTX is for use with 108ase-T or 1008ase-TX LAN segments, using an 8-pin (4-pair) RJ45 connector for the network cable. Be sure that all cabling used with the AT-2450TX in a 108ase-T segment is of Category 3, 4, or 5, and that all cabling used in a 1008ase-TX seement is of Category 5.

Important cable considerations: Fiber—The cable must comply with the appropriate IEER 802, standard for 62,2162 pm multimode fiber cable. The cable between the computer and the hub must be less than 2000 meters long for full-duplex operation and 412 meters long for half-duplex operation. The transmit circuit of the adapter card is connected to the receive circuit of the hub and vice versa.

If you inserted the card BEFORE running WINPREP. .

- ... you must run WINPREP, remove default drivers, and install new drivers:
- i. Kun Winrki
- 2. On the Windows desktop, right-click "My Computer" and select "Properties".
- 3. (Windows 2000 only) Select the "Hardware" tab.
- 4. Select "Device Manager"
- 5. Double-dick "Network Adapters".
- 6. Highlight the driver name that begins "AMD PCNet ..." or "Allied Teles vn ...".
- 7. Select "Remove
- (Windows 95 only) From the Start menu, select "Settings", "Control Panel". Right-Elick "Network" and select "Properties". If a driver name that begins "AMD PCNet..." or "Allied Telesyn"..." appears, highlight it and select "Remove".
- 9. Reboot the computer. Proceed with Step 3, Install Drivers.

3 Install Drivers

Windows 2000 automatically installs and loads drivers into memory with no reboot required. If you are using Windows 9x, you may be prompted for the Windows 9x CD during the process. Re-boot the system when Windows prompts for it. (If Windows 2000 displays a "Digital Signature Not Found" dialog box, cikk "Yes" to continue the installation.) Refer to the Microsoft operating system documentation to configure network clients and protocols.

Installation—Windows NT, Versions 3.5x and 4.0 / Windows for Workgroups, Version 3.11

IMPORTANT—Step-by-step instructions for each of these Windows versions are found on the CardAssistant CD in the INFO directory.

The standard Windows installation procedure is to insert the dapter card in a PCI slot according to Step 2, Install the Adapter Card. Once the adapter card is seated in a PCI slot and the computer's cover is back on, plug in the cable, turn on the power, and boot into Windows.

NOTE: If the computer in which you are installing the adapter card does not have a CD-ROM drive, you can create installation diskettes on one that does. From the CardAssistant CD, choose the "Create Diskettes" link to copy the needed files to two blank formatted 3½ inch floppy diskettes.

The Allied Telesyn AT-24_27 CardAssistant CD provides drivers for Windows NT version 3.5, 3.5 and 4.0, and version 3.11 of Windows for Workgroups. If you don't know your Windows version, open the Microsoft Windows System Control Panel. Pick the driver you need from the following table so that you can point Windows to the right directory on the CardAssistant CD or diskette during installation.

Operating System	Release	Driver	Lo catio n
Windows NT	3.5 x	ND1S3	*\ndis3
	4.0	NDIS4	* \
Windows for Workgroups	3.11	NDIS3 / NDIS2	*/

- *On the CD, the path to the location begins:
- <DRIVE>:\DRIVERS\AT2450_2700
- On the diskette, the path to the location begins:

LED Functions

The AT-2450FTX Fast Ethernet adapter card has four LEDs: The top (green) Full Duplex and Link LEDs and the bottom (yellow) 100 Mbps and Activity LEDs.

FD	
On	Indicates Full Duplex Mode
LNK	
On	Indicates a valid network connection on the port (UTP or fiber)
100	
On	Indicates the port connection is operating at 100 Mbps (100Base-TX)
Off	Indicates the RJ45 port connection is operating at 10 Mbps (10Base-T)
ACT	
On (flashing)	Indicates data is being exchanged

Pleatein 15 april The backtass of an emphotic To

Ones of the Texases are the This per sheel is she igned for a maximum ambient temperature of 91 degrees C. ALL COUNTRIES In till on duct in accordance with local and National Electrical Code

MeMorrobe Stateshell ENGISTS Day & Lein LED Produkt der Klasse II

A WARNUNG Nicht drekt in den Straft blicker RETURNS TEMPERATUR Die in Produkt wurde für den Belrids in diner Umgebungstemperatur von nicht mehr als ir 31° C.

AT THE R S MINISTER CONTROL OF THE C

TUYENG BILULIBILGS ASSI

Delegated PRODUKT UNDER KLASSE LIED A DESCRIPTION OF THE OWNER BETENINGSTEMPERATUR

Wenny Daniel landing the Later beam

Did to appear to refer to memorial in a simple order temperatur pi maksimum 31 grader C. ALLE LANDE: in talking of our doklet skal ske i sverenst emmelte med lokal se national lovelyning for

ENLISTS

DI it on "KLASSE | LED-PRODUKT" REDUCEST EMPERATORS

De a magricul empre la un voir del madaté mas net mor hechaem den till andm Celain ALLE LANDEN: het trettel installeren overwerkernt ig de lokale en nationale elektrische voorschriften

Securité électrique TUYENHEEL ULBEL OF A SEE

AT TENTION No pur fixer to fair search der years

TEMPÉR ATURE DE FONCTI ONNEMENT Ce mulétiel et l'expuble de l'olérer une l'empérature ambiante maximum de 31 degrés Cels iu

POURTOUS PASS : Installer le matériel en mémon aux na monéfice réque nu le rules es le ca

Timi in "ENSIMMÄISEN LUOKAN VALODI ODI TUOTE" A VARIOTUS Ali latin i il erien.

KÄYTTÖLÄMPÖTILA

Timi Instean appropriate special win Imagember (mailtight) 11 C NAUNY! MAAT: Account for it milesticien is knowliken oblide or wells or making the medical of

NORME DI SI CUREZZA EN 1923 Our le è un "PRODOT TO CO N LED DI CLASSE ACERTENZA Non Brure il reggio con gli occhi

TEMPERATURA DI BUNZIONAMENTO TEMPERATURA DI PUNZIONAMENTO

Quelle prodelle è co nceptie per una l'amperatura ambientale massima di 31 gradi centignati TELETT I PARS Is including it not do the in conformity delik visuali na mostive elettriche nazional

TUYENG DILULID LOS ASSI Delle et el "KLASSE I LED PRO DUKT" ADVARSAL Stirr ikke på it rålen.

Del le produktel er kom (ruer) for bruk i maksimum romtemperatur på 51 orader cek ins ALLE LAND: Produktel mi im laterer i ram var med de lukale se moje nale dektriske kode

20/15/O Não elhe fixamente para e rate

TEMPERATURA DE MINCIONAMENTO Die produkt fil projekade para uma lemperatura ambiente mixima de 31 grata centigrada:

Securidad eléctrica EN 1923

D Is to un "PRODUCTO DE DI ODO LUMI NISCENTE (LED) CLASE I" ADVERTENCIAL Na miral filamente el ha TEMPERATURA REQUESE DA PARA LA OPERACIÓN

To be per ducto colá dischado para una lemperatura ambiental máxima de 50 grado : C.

PARA TO DOS LOS PAISES: Mente di preducte de accurrde con les Cidiens Eléctricos locate y nacionales

Elitherhel

TOWNS OF THE STATE OF STREET Della ir en "KLASS I D'S DIODPRO DUKT"

WARNING Lucritating nirentelentr appen. DRIFTS TEMPERATUR

Denne medick i in he is invested for number mention of it would sands Manufer Colors 45 5 45 SNDES in talken models in ignlished and taken a chelating bedlimmely of relebitish nimulaing

Compliance Information **FCC Class B Certification**

Allied Teles yn International Corporation

Model Numbers: AT-2450FTX This device complies with Part 15 of the FCC Rules. Operation is subject to the following conditions

1) This device may not cause har mful interference, and

2) This device must accept any interference received, including interference that may cause undesired operation

Warning: This equipment has been lested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the PCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and if not installed and used in accordance with the instructions may cause harmful interference to radio or television recention, which can be determined by turning the equipment of and on, the user is encouraged to try to correct the interference by one or more of the following measures:

-Reorient or relocate the receiving antenna - Increase the separation between the equipment and receiver

- Connect the equipment into an outlet on a circuit different from the one which the receiver is connected to

- Consult the dealer or an experienced radio/TV technician for belo-

You are cautioned that changes or modification not expressly approved by the party responsible for compliance could mid mur authority to operate the equipment Attach unshielded or shielded twisted-pair cable to the RJ45 port and 62.5/125 µm

multi-mode cable to the fiber port. Note: In order to maintain compliance with the limits of a Class B digital device, Allied Telesyn requires that you use a quality interface cable when connecting to this device. Changes or modifications not expressly approved by Allied Teleson could void the user's authority to operate this equipment. Suggested cable type is 625/ 125 μm multi-mode cable for the fiber port and 100 Ω shielded or unshielded Category 3, 4, or 5 cable for the RJ45 port in 10 Mb mode, and 100 \Omega shielded or unshielded Category 5 cable for the R145 port in 100 Mb mode.

Industry Canada

This digital apparatus does not exceed the Class B limits for radio noise emissions from digital apparatus as set out in the radio interference regulations of Industry

Cet appareil numérique respecte les limites de bruits radioélectriques applicables aux appareils numériques de Classe B prescrites dans la norme sur le matériel brouilleur: "Appar eils Numéroues". NMB-003 édictée par l'Industrie Canada.

EN55022 Declaration of Conformance

This is to certify that the Allied Teles on AT-2450 is shielded against the generation of radio interference in accordance with the application of Council Directive 89/ 336/EEC, Article 4a. Conformity is declared by the application of EN55022:1987 Class B (CISPR 22:1984/BS 6528:1988).

CE Mark Declaration of Conformance

This is to certify that this product complies with ISO/IEC Guide 22 and EN45014.1t conforms to the following specifications:

E N55022(1998)/DIS PR-22]](1985) IEC 1000-4-2(1995) 4kV CD, 8kV AD TEC 1000-4-3(1995) 3 W/m IEC 1000-4-4(1995) 1kV - (power line) IEC 1008-4-6 (1995)

This product complies with the requirements of the Low Voltage Directive 73/23/EEC and the EMC Directive 89/336/EEC

AT-2450FTX **Fast Ethernet** Network Adapter Card

OUICK INSTALL

Warranty

Allied Telesyn warrants to the original owner that the product delivered in this package will be free from defects in material and workmanship for the lifetime of the product. There will be a minimal charge to replace consumable components. such as fuses, power transformers, and mechanical cooling devices. The warranty does not cover the product if it is damaged in the process of being installed. Allied Telesyn recommends that you have the company from whom you purchased this product install it THE ABOVE WARRANTY IS IN LIEU OF ANY OTHER WARRANTY

WHETHER EXPRESS, IMPLIED, OR STATUTORY, INCLUDING BUT NOT LIMITED TO ANY WARRANTY OF MERCHANTABILITY FITNESS FOR A PARTICULAR PURPOSE OR ANY WARRANTY ARISING OUT OF ANY PROPOSAL SPECIFICATION OR SAMPLE, ALLIED TELESYN SHALL NOT BE LIABLE FOR INCIDENTAL OR CONSQUENTIAL DAMAGES ALLIED TELESYN NEITHER ASSUMES NOR AUTHORIZES ANY PERSON TO ASSUME FOR IT ANY OTHER LIABILITY

Copyright

© 2000 by Allied Telesyn International Corporation. All rights reserved.

No part of this document may be copied or reproduced in any form or by any means without the prior written consent of Allied Telesyn International Corporation.

Allied Telesvn makes no warranties with respect to this documentation and disclaims any implied warranties of merchantability quality or fitness for any particular purpose. The information in this document is subject to change without notice. Allied Telesyn reserves the right to make revisions to this publication without obligation to notify any person or entity of any such changes

Allied Telesyn International Corporation 19800 North Creek Parkway, Suite 200

Bothell, Washington 98011

HSA Toll Free 1.800.424.5012

Technical Support 1.800.424.52.84

Allied Telesyn is a trademark of Allied Telesyn International Corporation, Other trademarks or brand names mentioned herein are trademarks or registered trade marks of their respective companies. PN 613-50124-00 Rev. A

✓ Allied Telesvn